



# WILLIAM HERRAIRS SCHOOL REPAIRS




REPAIR REPORT

June 16,2021


#### **TABLE OF CONTENTS**

## 1.PRE REPAIRS PHOTOS 2.PROGRESS PHOTOS






















MECHANICAL INSULATION AND SHEETROCK REPAIR



MECHANICAL INSULATION AND SHEETROCK REPAIR



PIPE INSULATION & STRUCTURAL DAMAGE REPAIR

